| Item | Qty<br>-243 | Part Number     | Description                        |  |
|------|-------------|-----------------|------------------------------------|--|
| 1    | Х           | D206-667-243    | CROSSTUBE ASSEMBLY (206L HIGH AFT) |  |
| 2    | 1           | D6004-115       | CROSSTUBE                          |  |
| 3    | 2           | D2873-043       | NUT PLATE                          |  |
| 4    | 2           | D2873-045       | NUT PLATE                          |  |
| 5    | 2           | D2892-1         | SUPPORT                            |  |
| 6    | 4           | D3595-063-450   | RUBBER CUSHION                     |  |
| 7    | 4           | MS21920-22      | CLAMP                              |  |
| 8    | 14          | MS20601AD4W10   | RIVET (OR NAS9302B-4-10)           |  |
| 9    | A/R         | PROSEAL 890 B-2 | SEALANT, AMS-S-8802 CLASS B-2      |  |

## **GENERAL NOTES:**

1) MATERIAL: MANUFACTURED FROM D6004-115

FINISHED LENGTH = 104.91±0.020

2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2 PAINT OUTSIDE PER DART QSI 005 4.2

- TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED.
- UNITS: INCHES UNLESS OTHERWISE NOTED.
- BREAK SHARP EDGES: 0.005 TO 0.010 MAX.
- IDENTIFICATION: SCRIBE DART PART NUMBER "D206-667-243" AND BATCH NUMBER ON INSIDE OF CUFF USING VIBRATING STYLUS.
- WEIGHT: 21.9 lbs
- PART IS SYMMETRIC ABOUT CENTERLINE.
- RUN CUTTER OFF PART WHERE INDICATED. BLEND OUT EDGE LONGITUDINALLY, TRANSITION SHOULD BE SMOOTH.
- 10) BEND PROGRESSIVELY WITH A MINIMUM OF 8 PASSES. MAXIMUM TUBE FLATTENING DUE TO BENDING IS 6% BASED ON O.D.
- 11) LIQUID PENETRANT INSPECT OUTSIDE SURFACE OF CROSSTUBE PER QSI 038.
- /D\ 12) TO INSTALL D2892-1 SUPPORT: ABRADE MATING SURFACE OF SUPPORT AND CROSSTUBE WITH 180-GRIT SANDPAPER AND REMOVE RESIDUE WITH MEK (OR EQUIVALENT). APPLY A 0.04" TO 0.07" THICK LAYER OF PROSEAL 890 CLASS B-2 (OR AMS-S-8802 CLASS B-2) SEALANT TO MATING SURFACE OF SUPPORT.
  - 13) INSTALL MS21920-22 CLAMPS WITH D3595-063-450 RUBBER CUSHIONS TO SECURE THE D2892-1 SUPPORT ON TOP SIDE OF THE CROSSTUBE. ENSURE CLAMP MECHANISMS ARE LOCATED ON CROSSTUBE SUPPORTS.
  - 14) EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLENDED OUT LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE.

/D\ 15) TORQUE CLAMPS 80 TO 100 IN-LB. ENSURE AT LEAST 1.5 THREADS ARE SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING. PRIOR TO PACKAGING, RE-CHECK TORQUE ON CLAMPS AFTER PROSEAL 890 SEALANT HAS CURED FOR 72 HOURS.

RELEASED 2018 SEP 06 4

| IXLV.      | DESCRIPTION |   | י ויטן      | שאוב    |
|------------|-------------|---|-------------|---------|
| DESIGN     | P           | DART AEROSPACE LTD  |             | D       |
| DRAWN      | JMH         | HAWKESBURY, ONTARIO, CANADA   |             |         |
| CHECKED    | ZF          | DRAWING NO.   |             | REV. D  |
| MFG. APPR. | SES         | D206-667-243  | SHEE        | T1 OF 4 |
| APPROVED   | NO.         | TITLE   |             | SCALE   |
| DE APPR.   | 41          | CROSSTUBE ASSY (206   | L HIGH AFT) | NTS     |
| DATE 18.0  | 5.01        | COPYRIGHT © 2000 BY DART AEROSPACE LTD  THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS  NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT |             |         |

EN18-797

8





